

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	32373	spindle WITH position	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:21
S2	41612	spindle WITH position\$3	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:06
S3	214	S2 SAME (distance WITH time)	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:45
S4	0	S3 SAME triangulation	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:24
S5	3	S3 AND triangulation	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:24
S6	39	S2 SAME (distance WITH time). ab.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:24
S7	157	S2 SAME (distance WITH time)	USPAT	OR	OFF	2005/06/14 15:41
S8	39314	electromagnetic WITH (signal OR signals)	USPAT	OR	OFF	2005/06/15 13:03
S9	4	S7 AND S8	USPAT	OR	OFF	2005/06/14 15:25
S10	1	"6311803".pn.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:44
S11	73802	(machine OR machining) WITH tool	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 09:35
S12	2925	S11 WITH S2	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:44
S13	4149	S2 SAME distance	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:45
S14	276	S12 SAME S13	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:46
S15	207	S12 SAME S13	USPAT	OR	OFF	2005/06/14 15:46
S16	2	S15 SAME S8	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:48
S17	373	(measure OR measurement OR measuring) SAME S13	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/14 15:49
S18	260	(measure OR measurement OR measuring) SAME S13	USPAT	OR	OFF	2005/06/15 09:53
S19	47	(measure OR measurement OR measuring) SAME S13.ab.ti.clm	USPAT	OR	OFF	2005/06/14 15:51

S20	19	(measure OR measurement OR measuring) SAME S13.ab,ti.	USPAT	OR	OFF	2005/06/14 15:51
S21	42978	spindle WITH (position\$3 OR location\$)	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 09:35
S22	2353	S21 WITH distance	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 09:35
S23	3019	((machine OR machining) WITH tool) WITH S21	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 09:36
S24	173	((machine OR machining) WITH tool) WITH S22	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 09:36
S25	8	(measure OR measurement OR measuring) SAME S24	USPAT	OR	OFF	2005/06/15 10:02
S26	7	S22 AND triangulation	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 10:03
S27	39314	(electromagnetic WITH (signal OR signals))	USPAT	OR	OFF	2005/06/15 13:08
S28	13	((machine WITH tool) WITH spindle) SAME S27	USPAT	OR	OFF	2005/06/15 13:04
S29	15	((machin\$3 WITH tool) WITH spindle) SAME S27	USPAT	OR	OFF	2005/06/15 13:05
S30	42978	spindle WITH (position\$3 OR location\$)	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:05
S31	2353	S30 WITH distance	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:12
S32	173	((machine OR machining) WITH tool) WITH S31	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:10
S33	0	S32 SAME S27	USPAT	OR	OFF	2005/06/15 13:05
S34	0	S32 AND S27	USPAT	OR	OFF	2005/06/15 13:05
S35	31	(spindle WITH position\$3) SAME S27	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:08
S36	379	(electromagnetic WITH (signal OR signals)) WITH (time WITH measur\$4)	USPAT	OR	OFF	2005/06/15 13:08
S37	0	(spindle WITH position\$3) SAME S36	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:08
S38	1	(spindle WITH position\$3) AND S36	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:10
S39	79	position\$3 SAME S36	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:13

S40	0	((machine OR machining) WITH tool) SAME S39	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:10
S41	4	((machine OR machining) WITH tool) AND S39	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:10
S42	0	S31 SAME S36	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:12
S43	0	S31 AND S36	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/06/15 13:12